

PAINT MASK INSTALLATION INSTRUCTIONS


1. Prep the surface for the mask to be applied. Make sure there is no debris.
2. Position and tape the mask to the surface it is to be applied. Tape the mask on both top and bottom as seen in **diagram 1a**.

3. Now you are ready to remove the underlying paper liner of the mask. Untape the mask at either end that you want to start applying the mask to the surface. Only remove the tape no more than the half way point. You do not want to work with too much material at a time as this will make it difficult to apply and even ruin the mask.




Once the tape is removed on top and bottom only half way pull back the mask from the underlying paper liner. Pull the mask so the paper liner is visible and again only proceed to the half way point. Now that this has been done, Take a blade and cut away the paper liner that is exposed.

See **diagram 1b**




4. Now pull the exposed mask back to the forward position it was originally. Make sure it does not stick yet to the surface that you are placing the mask on. Once you do this you are ready to apply the mask. To do so, have even tension on top and bottom of the mask that is being held. Now from the half way point where you cut the paper liner start to lay the mask in an up and down motion going outward.

See **diagram 1c**



5. Once you have applied this half of the mask, you can repeat the steps for the other half of the mask.

- Untape the remainder of the mask top and bottom
- Pull back the paint mask to the end of the paper liner
- Remove the paper liner
- Pull the mask back to its original position to where it will lay
- Begin moving in an upward and downward and outward motion
- to apply the mask.



6. Now remove the areas that you laid that you need to paint by simply pulling it off the surface. If you need to paint several lines etc. put the piece you pull off on the surface above the mask on the surface so you can use it later.

See **diagram 1d**

If there is a second line after the painted area dries, place the mask piece that was removed for painting and place it on the newly painted area. After that is done now remove the second line that is needed to be painted.

